

BESA License Key 2.0 - External Release Notes

Documents are subject to workflows, and content shall only be used if the content is approved (indicated by a green ring-symbol)

● Approved , Changed on: October 11th 2023 at 12:06:02 PM (UTC)



External Release Notes

Table of Contents

- [External Release Notes](#)
 - [BESA License Key Release Notes](#)
 - [Version 2.0.1.0](#)
 - [HASPUserSetup.exe \(V. 9.12\):](#)
 - [Previous Versions](#)
 - [Version 2.0.0.0](#)
 - [Sentinel HL NetTime 10 \(V. 6.08\)](#)
 - [HASPUserSetup.exe \(V. 8.21\):](#)
 - [Page ID](#)
 - [Change History \(valid revision number\)](#)
 - [Attachments](#)
 - [Product Change Notification- Sentinel HL](#)
-

BESA License Key Release Notes

Version 2.0.1.0

HASPUserSetup.exe (V. 9.12):

Info

HASPUserSetup.exe is a GUI-based installation program to install the run-time environment for the BESA License Keys.

This utility is supplied by BESA license key manufacturer Thales and is provided by BESA as is.

The utility and the corresponding readme file are located in \Utilities\License\System folder of the installation directory of BESA programs.

Improvements / Bugfixes / Residual anomalies

- When installing the RTE on a machine where Fabula Tech USB over Network is installed, installation of the RTE hangs.
Workaround: Disconnect the HL key before running the RTE installer.

For the complete list of known issues provided by Thales, please refer to the Readme.html file in \Utilities\License\System folder of the installation directory of BESA programs.

Previous Versions

Version 2.0.0.0

Sentinel HL NetTime 10 (V. 6.08)

Improvements

- **Updated versions V. 4.31/V. 4.34 to 6.08**
 - BESA License Keys were updated with an alternate smart card chip. These keys are fully backward compatible. To help visually identify the different key version: The silver keyring was replaced with a gold keyring. (Please refer to attached document RoxtraID 92388 - Product Change Notification- Sentinel HL.pdf, Rev. 001/09.2021)

Bugfixes

None

Residual anomalies

None

HASPUserSetup.exe (V. 8.21):

Improvements / Bugfixes / Residual anomalies

- Please refer to the Readme.html file in \Utilities\License\System folder of the installation directory of BESA programs.

Additional Known Issues (older versions)

Affected Tool + Version	Publication Date	Information
HASPUserSetup.exe (V. 7.100 and older)	November 2021	<p>[KB0021742]</p> <p>Upgrade of Windows 10 to version 2004 may fail when working with run-time environment installed by HASPUserSetup.exe version 7.100 or earlier</p> <p>Please refer to the original manufacturer article for more information and workarounds: link to KB0021742</p>

Page ID


190611486

Change History (valid revision number)

Version	Effective Date	Approvals	Version Notes
1	Wed, Oct 11, 2023, 09:24:52 AM	>> *Action: approve, MK, Approval: QM Approval (State: QM Approval, Wed, Oct 11, 2023, 09:24:52 AM)	None
2	Wed, Oct 11, 2023, 12:06:02 PM	>> *Action: approve, MK, Approval: QM Approval (State:	None

Version	Effective Date	Approvals	Version Notes
		QM Approval, Wed, Oct 11, 2023, 12:06:02 PM)	

Attachments

Attachment	Description
Product Change Notification- Sentinel HL  RoxtralD 92388 - Product Change Notification- Sentinel HL.pdf	Product Change Notification- Sentinel HL

CONFIDENTIAL, printed version is NO controlled document and NOT subject to modifications